

# Accident / Incident Report Closed



Unit/Department	Process Area	Site	Report Number
South Operation-Elyria		ELYRIA	0084-SOPS-14-0035
Report Date	Incident Date	Incident Time	Copied From
03/09/2014	03/08/2014	11:15 PM	
Incident Location		Team Leader / Supervisor	Reported By
Building 31 Gen Cat (#3 Calciner)		Robert Scoggins	Robert Scoggins
Title of Event (Limit to 90 characters)		Category	Division / Bus. Group / Subgroup Code
CTO Failure / NOx Release		<input type="checkbox"/> Safety & Health <input type="checkbox"/> Environmental	CC / G-CCP
Incident Classification			
<input type="checkbox"/> Near Miss <input type="checkbox"/> Process Safety <input type="checkbox"/> Injury / Illness <input checked="" type="checkbox"/> Spill / Release <input type="checkbox"/> Permit / Regulatory Deviation <input type="checkbox"/> Fire <input type="checkbox"/> Odor Complaint <input type="checkbox"/> Property Loss <input type="checkbox"/> Citation / NOV <input type="checkbox"/> Health Exposure <input type="checkbox"/> Inspection <input type="checkbox"/> Major Incident <input type="checkbox"/> Non-Occupational <input type="checkbox"/> RMP <input type="checkbox"/> Contractor <input type="checkbox"/> Contractor Injury / Illness <input type="checkbox"/> Contract Injury / Illness <input type="checkbox"/> PSM <input type="checkbox"/> Plant Upset <input type="checkbox"/> EHS Management System Failure <input type="checkbox"/> Other			
Describe Event / What Happened			
<p>On Saturday March 8, 2014 at approximately 11:15 pm, several shift personnel detected a NOx odor on the 2nd floor of building 31 near the National Dryer. Shift personnel checked the 1st and 2nd floors with NOx meters, and discovered that the release originated from #3 calciner. It was quickly noticed that there was little to no suction registering on the calciner exhaust magnahelic gauges. It was then presumed that the CTO experienced a malfunction (calciner exhaust was not being pulled to the CTO unit).</p>			
Immediate Corrective Action or Response			
<p>Due to an engineering interlock between the syntron feeder and the Calciner, the feed automatically shut off, calciner exhaust was diverted to the F1 scrubber, and the building was evacuated. After confirming all personnel accounted for, the ERT team gathered and prepared for SCBA entry to further investigate #3 calciner, and to evaluate NOx levels throughout the building. Entry team confirmed NOx levels returned to zero on all floors of building 31, and "all clear" given to personnel.</p>			
Immediate Cause			
<p>Upon returning to the building, Wonderware was reviewed. It was discovered that at 11:06 pm due to equipment interlocks between the CTO and the syntron the calciner feed was automatically stopped as the malfunction occurred.</p>			
Spill Release Type(s)		Non RQ Spill / Release	
Chemical(s) Involved	CAS #	Phy. State	Air   Land   Water   Contmt   Units
Nitrogen Dioxide (NOx)	10102-44-0	Gas	1.66   0   0   0   lbs
Disposition of Material	Release to air		
Weather Conditions	Skies:	Temperature:	Wind Direction:   Wind Speed:

Cause Narrative			
Electrical short on the VFD caused the CTO to shut down.			
Contributing Causes		Root/Primary Causes	
Loose wiring on the VFD on the blower caused an electrical shortage which led to the CTO failure.		28 - Equipment Reliability Program Implementation LTA	
Operations was unsure of the mechanics of what occurs during scrubber failure.		192 - Communications	29 - Corrective Maintenance LTA
		194 - No Communication or	31 - Repair Implementation LTA
		197 - Communication Between Shifts and Management LTA	

<p>During the CCR update, the link between CTO and F1 scrubber was severed. The link would have automatically caused the suction to route to F1 when the CTO failed.</p> <p>VFD was installed 2 - 3 years prior. It is assumed that the connections either became loose over time or were loose from installation. There were no maintenance checks on the VFD during this time.</p>	Not Timely		
	15 - Design Input/Output	17 - Design Output LTA	17 - Design Output LTA
	28 - Equipment Reliability Program Implementation LTA	36 - Predictive Maintenance LTA	38 - Monitoring LTA

**Explanation of Root Causes**

**192/194/197 - Newly implemented change caused the syntron to automatically shut off when CTO failed. Operations was not aware of this change.**

Any known or potential off-site impacts?	No	PSM Incident?	No	Estimated Cost:	2,000.00 USD
Investigation Team	William D Deisenroth; Jefferson Lewis; Robert Scoggins; Jennifer Bailey				

Item	Corrective Action(s) to prevent recurrence	Responsible Person	Target Date	Final Closed Date	VC Req	VE Req
1	Investigate adding a PM to VFD's for loose connections using either thermography or physical inspection.	Gregory A Menz/BASF-CATALYSTS/BASF	04/18/2014	08/25/2014	N	N
2	Investigate better mechanism for communicating changes (MOC) within the plant and assuring MOC's are entered for changes impacting equipment functionality.	Noemi Trent/BASF-CATALYSTS/BASF	05/31/2014	06/09/2014	N	N

**Approved By:**

Manager / Dept. Head	Leon Zavodnik	03/20/2014 02:25 PM
EHS Unit Coordinator	Tim Anglin	04/04/2014 08:07 AM
Employee	Robert Scoggins	04/04/2014 11:41 PM